

FITNESS CERTIFICATE OF SCHOOL BUILDING

1. Name of the Officer : Bessy John
2. Name of the School : Chinmaya Vidyalayam ,Vaduthala,,Ernakulam
3. Location with name of Education District/ Sub. District : Ernakulam.
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.
- Three Storeyed Building (1 No.)
- Two storeyed Building (1 No)
5. Period for which the certificate is issued :2024 -2025
6. Nature of defects , if any Nil
- a) Foundation and basement : RCC
- b) Superstructure : Wood.
- c) Doors and Windows ::Anjili wood and Steel Frame work
- d) Wood work wrought and put up :.R.C.C.
- e) Roof : Cement flooring
- f) Flooring
7. Any major defects noticed which will render the building unsafe in any manner : N.O
8. Whether maintenance works have been done properly : Yes
9. Whether the structure is sound or not for conducting classes :The Structure is Sound for Normal Weather Condition

Certified that the school building was inspected by me on 01/06/2024 and found to be fit to conduct classes for the period

2024-2025 under normal weather condition.

Place :.....Cochin

Date :01/06/2024.....



Bessy John
01/06/24
Assistant Engineer
BESSY JOHN
ASSISTANT ENGINEER
LSGD
KOCHI MUNICIPAL CORPORATION

CONFERENCE HALL 11.50 X 5.60 X 3.60 (1)

7.00 X 8.50 X 3.60 (1)

LAB 6.00 X 3.00 X 3.60 (1)

TOILET 6.00 X 6.00 X 3.60 (2)

LOBBY 6.20 X 4.00 X 3.60 (1)

SECOND FLOOR

CLASS ROOMS 9.10 X 6.00 X 3.60 (6)

6.00 X 6.00 X 3.60 (1)

STAFF ROOM 2.30 X 6.40 X 3.60 (1)

THIRD FLOOR

CLASS ROOM 9.10 X 6.00 X 3.60 (1)

READING ROOM 11.70 X 9.30 X 3.60 (1)

COMPUTER LAB 9.00 X 6.00 X 3.60 (2)

MATHS LAB 8.50 X 6.20 X 3.60 (1)

- 8 1) FOUNDATION AND BASEMENT : R C C
- 2) SUPER STRUCTURE : BRICK MANSONRY
- 3) DOORS AND WINDOWS : WOOD WORK
- 4) WOOD WORK WROUGHT & PUT UP :
- 5) ROOF : R C C
- 6) FLOORING : CEMENT FLOORING
- 7) MISCELLANEOUS (CRACKS , etc..) : NO
- 8 ANY MAJOR DEFECTS MODIFIED WHICH WILL
RENDER THE BUILDING UNSAFE IN ANY MANNER : NO
- 9 WHETHER MAINTENANCE WORKS HAVE BEEN
DONE PROPERLY : YES
- 10 WHETHER THE STRUCTURE IS SOUND OR NOT
FOR CONDUCTING CLASSES : STRUCTURE IS SOUND UNDER NORMAL
WEATHER CONDITION



Bessy John
11/6/14
BESSY JOHN
ASSISTANT ENGINEER
LSGD
KOCHI MUNICIPAL CORPORATION

MAIN BLOCKGROUND FLOOR

CLASS ROOM	6.00 X 6.00 X 3.60 (17)
LOBBY	12.50 X 5.90 X 3.60 (1)
	8.40 X 6.00 X 3.60 (1)
STAFF ROOM	2.30 X 6.40 X 3.60 (1)
	5.50 X 6.00 X 3.60 (1)
PASSAGE	88.40 X 2.80 X 3.60 (1)
	16.50 X 2.80 X 3.60 (2)
TOILET	12.60 X 3.10 X 2.60 (1)
	9.30 X 8.40 X 3.30 (1)
STAIR	6.40 X 2.80 X 3.60 (2)
SCIENCE LAB JUNIOR	8.00 X 6.30 X 3.60 (1)
CANTEEN	18.50 X 5.60 X 3.60 (1)

FIRST FLOOR

CLASS ROOMS	9.10 X 6.00 X 3.60 (6)
	6.00 X 6.00 X 3.60 (5)
STAFF ROOM	2.30 X 6.40 X 3.60 (1)
	5.50 X 6.00 X 3.60 (1)
OFFICE	12.50 X 6.00 X 3.60 (1)
	8.40 X 6.00 X 3.60 (1)

SECOND BLOCKGROUND FLOOR

CLASS ROOMS	6.00 X 6.00 X 3.60 (9)
	9.00 X 6.00 X 3.60 (1)
STAFF ROOM	6.00 X 6.00 X 3.60 (2)
WASH ROOM	6.00 X 3.00 X 3.60 (1)
TOILET	6.00 X 2.10 X 3.60 (1)
PASSAGE	13.70 X 1.90 X 3.60 (1)
	21.90 X 2.10 X 3.60 (1)
	19.10 X 3.00 X 3.60 (1)
	15.80 X 2.10 X 3.60 (1)

FIRST FLOOR

CLASS ROOMS	6.00 X 6.00 X 3.60 (9)
	9.00 X 6.00 X 3.60 (1)
STAFF ROOM	6.00 X 6.00 X 3.60 (2)
WASH ROOM	6.00 X 3.00 X 3.60 (1)
TOILET	6.00 X 2.10 X 3.60 (1)
PASSAGE	13.70 X 1.90 X 3.60 (1)
	21.90 X 2.10 X 3.60 (1)
	19.10 X 3.00 X 3.60 (1)
	15.80 X 2.10 X 3.60 (1)



B. J.
11/6/24
BESSY JOHN
ASSISTANT ENGINEER
LSGD
KOCHI MUNICIPAL CORPORATION